


AS00.00-Z-0009-01A	Risk of injury . Moving parts can pinch, crush or, in extreme cases even sever extremities.	No parts of the body or limbs should be within the operating range of the mechanism when moving components.	 Danger !
--------------------	----------------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------

MODEL ALL

Risk of injury

When working on components which can be moved either by hand, by means of electric motors, or hydraulically/pneumatically via a connecting mechanism, serious injuries can occur due to body parts being cut, pinched or crushed.

Safety instructions/precautions

- Monitor hazard area.

- Secure the operating area of the mechanism against interference when components are in motion.
- Never touch the mechanism of a component while it is being actuated by electric motors via STAR DIAGNOSIS or by direct actuation (terminal 30).
- Choose a test cable of sufficient length.