
## MODEL 230

with CODE 801 (Model year 2001) with CODE 802 (Model year 2002) with CODE 803 (Model year 2003) with CODE 804 (Model year 2004) with CODE 805 (Model year 2005) with CODE 806 (Model year 2006) with CODE 807 (Model year 2007) with CODE 808 (Model year 2008)

# Service B



P00.00-4902-11

Customer: -	Order number: -			
VIN/license plate number: WDB2304751F077344	Miles: 66000			
Service code: B	Workshop code: -			
Remaining distance: -	Remaining time: -			
Oil type/viscosity: - *Mercedes-Benz oil recommended	Completion time/date: 0	Completion time/date: 09.01.2015		
Service consultation performed at vehicle	Yes: -	No: X		
Notes/explanations: -				
The following activities are hereby confirmed: - Completion of relevant service operations				
Signature				
	Input condition not OK:	$\otimes$		
Completed				
$\boxtimes$				

Service reception

© Daimler AG, 1/9/15, G/01/15, ap00.20-p-1265lab, SERVICE SHEET for Service B, up to code 808 MODEL 230 with CODE 801 (Model year 2001) with CODE 802 (Model year 2002) with CODE 803 (Model year 2003) with CODE 804 (Model year 2004) with CODE 805 (Model year 2005) with CODE 806

	The completely edited reception report for service on vehicle is available		0	
		<b>i</b> To be performed by the service advisor. The service scope is only completely performed when all acceptance items and the maintenance items listed in the service sheet have been fully processed.		AP00.20-P-0009Z
	Brake system Perform brake test and enter the result in the table		0	AP42.00-P-4290BA
	Vehicle front end, vehicle rear end Check exterior lights for proper operation		0	71 42.001 42000/
	Check and correct the adjustment of the headlamps		0	AP82.10-P-8252EW
		<b>i</b> Correct xenon headlamps, invoice as an additional operation.		AP82.10-P-8260R
	Vehicle interior Check lamps in instrument cluster and interior illumination		0	AP54.30-P-5452C
	Check windshield wipers, windshield washer system and headlamp cleaning system for proper operation		0	Aro4.30-r-04020
	Sensotronic Brake Control (SBC™): Check acoustic warning system	Vehicles with Sensotronic Brake Control (SBC™)	0	AP82.30-P-8252V
	Sensotronic Brake Control (SBC <sup>™</sup> ): Check hydraulic unit	Vehicles with Sensotronic Brake Control (SBC™)	0	AP54.30-P-5450A
	Check seat belts and buckles for external damage and correct operation		0	AP42.50-P-4259A
	Replace activated charcoal dust filter			AP91.40-P-9150M AP83.00-P-8384R
	Engine compartment			AP83.00-P-8384R
	Check water drain in air-water duct and clean if necessary		0	AP83.10-P-8353A
	Brake system: Check fluid level		0	AF03.10-F-0333A
П	Check visible area of poly-V belt for wear		0	AP42.10-P-4210Z
_		ENGINE 112, 113 ENGINE 272, 273 ENGINE 275	-	AP13.22-P-1352Z AP13.22-P-1352RX AP13.22-P-1352L
	Power steering: Check oil level		0	AF 13.22-F-1302L
	Active Body Control (ABC): Check/correct oil level		0	AP46.00-P-4612SLC
		With code 487 (Active Body Control (ABC))	-	AP32.50-P-3213I
	Engine cooling system: Check fluid level, corrosion/antifreeze content	ENGINE 112, 113 ENGINE 272, 273 ENGINE 275 Main and low- temperature circuit	0	AP20.00-P-2010Z AP20.00-P-2010RX AP20.00-P-2010H

© Daimler AG, 1/9/15, G/01/15, ap00.20-p-1265lab, SERVICE SHEET for Service B, up to code 808 MODEL 230 with CODE 801 (Model year 2001) with CODE 802 (Model year 2002) with CODE 803 (Model year 2003) with CODE 804 (Model year 2004) with CODE 805 (Model year 2005) with CODE 806

		<b>i</b> Enter corrosion/antifreeze protection here:		
	Check all visible parts in engine compartment for damage and leaks	°C	0	
	Engine hood: Check latch and latch hook for		$\bigcirc$	AP00.20-P-0055EW
	ease of movement		0	AP88.40-P-8851R
	Check and correct battery fluid level	not with AGM battery	0	
	Windshield washer system: check/correct	·····,		AP54.10-P-5410A
	fluid level	 		AP82.35-P-8210N
	Engines Change ail and filter	<b>i</b> Use summer/winter cleaner depending on season.		
	Engine: Change oil and filter	ENGINE 112		AP18.00-P-0101AE
		ENGINE 113.963		AP18.00-P-0101GH
		ENGINE 113.992/995		AP18.00-P-0101R
		ENGINE 272 ENGINE 273		AP18.00-P-0101PIT AP18.00-P-0101SX
		ENGINE 275 ENGINE 275.951/954		AP18.00-P-0101SLA
		ENGINE 275.981		AP18.00-P-0101SZ
	Underside of vehicle		-	
	Check tires for damage and cracking and enter result in table		0	
				AP40.10-P-4051Z
	Inspect front axle joint for play, inspect rubber boots		0	
	Check track red and drea link linkage for		0	AP33.20-P-3353BA
	Check track rod and drag link linkage for play, check rubber boots		0	
-	Check propeller shaft flex disks for signs of		$\bigcirc$	AP46.00-P-4653F
	damage and deformation		U	AP41.10-P-4152Z
	Check all visible parts on vehicle underside for damage and leaks		0	
	-			AP00.20-P-0054EW
		<b>L</b> The country-specific regulations for mobility and body shell complaints apply.		
	Tires, brakes			
	Correct tire pressure and enter set tire pressure in the table		0	
				AP40.15-P-4061A
	Trunk		-	
	Check spare wheel tire pressure, correct and enter set tire pressure in the table		0	
	·	Vehicles with spare tire		
	TIREFIT puncture sealing compound -		0	AP40.15-P-4061A
	check expiration date		0	
		Vehicles fitted with TIREFIT		
		i Enter TIREFIT expiration date		AP40.10-P-4054R
		here:		
		When the TIREFIT expiration date is reached:		
		$\downarrow$		
		Replace TIREFIT, invoice as additional operation.		
	Check luggage compartment illumination for proper operation		0	
	Additional operations			

© Daimler AG, 1/9/15, G/01/15, ap00.20-p-1265lab, SERVICE SHEET for Service B, up to code 808 Page 3 of 4 MODEL 230 with CODE 801 (Model year 2001) with CODE 802 (Model year 2002) with CODE 803 (Model year 2003) with CODE 804 (Model year 2004) with CODE 805 (Model year 2005) with CODE 806

## Brake values

	Left	Right
Front		
Rear		
Parking brake		

# Condition and tread depth of tires

	Right front	Left front	Right rear	Left rear
Condition OK				
Condition NOK				
Tread depth				

## Set tire pressure in bar or psi

	Front axle	Rear axle	Spare wheel
bar/psi			